



Article  
 DEWALT DC920, DC930, DC935, DC936, DC940 Individual Cordless Drills  
 Safety Recall

**Safety Recall Notice**

**DEWALT DC920, DC930, DC935, DC936, DC940 Individual Cordless Drills Safety Recall**

DEWALT Industrial Tool Company is recalling to repair the following 12 Volt, 14.4 Volt, 18 Volt Heavy-Duty XRP™ Individual Cordless Drills. The trigger switch could over-heat which presents a possible risk of fire.

The following drills may be affected:			
Model Number	Description	Affected Date/Code Range	
DC920	Heavy-Duty XRP™ 1/2" (13mm) 18 Volt Cordless Drill/Driver	200723 200741	through
DC930	Heavy-Duty XRP™ 1/2" (13mm) 14.4 Volt Cordless Drill/Driver	200625 200746	through
DC935	Heavy-Duty XRP™ 1/2" (13mm) 14.4 Volt Hammerdrill/Cordless Drill/Driver	200627 200746	through
DC936	Heavy-Duty XRP™ 1/2" (13mm) 14.4 Volt Hammerdrill/Cordless Drill/Driver	200635 200746	through
DC940	Heavy-Duty XRP™ 1/2" (13mm) 12 Volt Cordless Drill/Driver	200635 200746	through

**ONLY DRILLS WITH THE MODEL NUMBERS AND DATE CODES LISTED ABOVE ARE AFFECTED**  
 Products stamped with an "M" following the date code have been repaired and are **NOT affected by this recall..**

The location of the date code is shown on the photograph below.



If your drill is affected, **STOP USING IT IMMEDIATELY**, and call DEWALT toll-free:  
 1-888-742-9168  
 Between 8:00 AM and 5:00 PM Eastern Time, Monday through Friday or go to  
 www.DEWALT.com

for the location of a service center to obtain a free inspection and repair, if necessary.  
 Recall done in cooperation with U.S. Consumer Product Safety Commission.